

RE

REGULATORY RECORD

RERA Document

The document as the regulator published it, reproduced in full behind this page.

Published for reference. The authority's own register is the operative record.

Form-5

Certificate by Architect / Licensed Surveyor

(Certificate for the purpose of completion of Layout/ Sub-Division Project)

Address of the Project : Layout project set up at S.F.No. – 368/1B1 and 368/1D1 Extent of 2.01 ½ Acres (or) 8154.41 Sq.mt, at Kadayampatti South Village and Kadayampatti Town Panchayat, Kadayampatti Taluk, Salem District.

Date : 06.05.2026

Name of the Promoter : **1. M.Loganathan, 2. S.Natarajan,
3. R.Sidhar and 4. R.Yuvaraj**

Address of the Promoter : D.No.171/1, Chettiyar street,
Thathiyampatti Village,
Kadayampatti Taluk,
Salem District - 636 309.
Mobile No. 82485 53234

Subject : Certificate for Layout project set up at S.F.No. - 368/1B1 and 368/1D1 Extent of 2.01 ½ Acres (or) 8154.41 Sq.mt, at Kadayampatti South Village and Kadayampatti Town Panchayat, Kadayampatti Taluk, Salem District.

Sir,

I, **A.SEENIVASAN**, Registered Engineer Grade - I (DTCP Registration No. – 14 / RE- I / 2024) had undertaken assignment as a Licensed Surveyor for the assessment and verification of development of work situated on the bearing Survey no. 368/1B1 and 368/1D1 demarcated by its boundaries (Latitude – 11.873820 and Longitude – 78.105893) the North – Vacant, South – Vacant Land, East – Vacant Land, West - Town Panchayat Road and Vacant land, Kadayampatti South Village and Kadayampatti Town Panchayat, Kadayampatti Taluk, Salem District. measuring 2.01 ½ Acres (or) 8154.41 Sq.mt. Being developed by **M.Loganathan, S.Natarajan, R.Sidhar and R.Yuvaraj** promoter Based on site inspection carried out by me with respect to each of the plot(s) of the aforesaid Layout Project, I certify that as on date of this certificate, the project has been developed and completed in all respects as per the Plotting layout plan sanctioned by District Town and Country Planning, Salem District vide Layout Approval No. 03/2026, Dated : 05.01.2026 including all amenities and facilities as committed by the promoter to the allottees.

Yours Faithfully,

Enclosed:

Photographs of all sides of site.

Er.A.SEENIVASAN, B.E.,
Registered Engineer Grade-I
Salem DTCP Regn.No. : 014/RE-I/2024
5/318-B, State Bank Colony-II
Junction Main Road, SALEM - 4.
Contact No. 98247-12227



GOVERNMENT OF TAMIL NADU
TOWN AND COUNTRY PLANNING DEPARTMENT

SALEM DTCP

THE SALEM DISTRICT TOWN AND COUNTRY PLANNING

Phone: 0427-2448625

Email: ddslmregion@gmail.com

Website: www.tn.gov.in/tcp

PROFESSIONAL REGISTRATION CERTIFICATE
RENEWED FROM 01.04.2024 TO 31.03.2029

This is to certify that **THIRU. A. SEENIVASAN** has enrolled as **Registered Engineer Grade-I (RE-I)** with Salem District Town and Country Planning who has the qualification of **B.E.(Civil)**, and experience in the relevant field for 37 years.

He has been given the **Registration No:14/RE-I/2024 (Renewal)**. He shall be required to comply with the duties and responsibilities prescribed by the Government of Tamil Nadu in Part V, "Registration of Professionals", Tamil Nadu Combined Development and Building Rules, 2019 approved vide G.O.(MS) No. 18, MAWS (MA1) Dept., Dated 04.02.2019.

This Registration is valid upto **31.03.2029**.



[Signature] 12/04/2024

ASSISTANT DIRECTOR,
DISTRICT TOWN AND COUNTRY PLANNING,
SALEM DISTRICT.

Eight ways to know a piece of land before you pay for it.

This report covers one part of the picture. These cover the rest, drawn from the same government records, for any property in Tamil Nadu.

LandLens One

Ask anything about a property and get an answer grounded in live government records, with the sources shown.

[/landlens/one](#)



Verify My Land

Every record check run on one property and returned as a single report.

[/landlens/verify-my-land](#)



Legal Opinion

An advocate's written opinion on the title, built on the records we pull for it.

[/landlens](#)



One Map

Every layer on one map: the parcel, its boundary, zoning, water bodies and what sits around it.

[/landlens/one/map](#)



PriceMap

What land actually changed hands for around this plot, taken from the registered deeds.

[/landlens/pricemap](#)



Build Scope

What you are allowed to build here: floor space, height, coverage and setbacks.

[/landlens/build-scope](#)



Property Tracker

Watch a property and hear about it when something new is registered against it.

[/landlens/property-tracker](#)



Deal Room

Run the transaction in one place: documents, stamping, signatures and the parties.

[/landlens/deal-room](#)



Twenty-four checks you can run yourself, at no cost.

Records and verification

The registers themselves, read for you.

Encumbrance Certificate

Patta and Chitta

Field Measurement Sketch

EC Analyzer

Bank charge check

Court case search

Seller background check

Approval check by survey

Value and duty

What it is worth and what it costs to register.

Guideline value by street

Guideline value by survey

Stamp duty and registration fees

Capital gains

Floor space index

Area unit converter

Zoning and land use

What the plan says can happen on this land.

Land use zone finder

CMDA land use check

Coastal regulation zone

Master plan check

Water bodies finder

Airport height clearance

Registers and directories

Who holds it, and which office keeps the record.

Find your registering office

Temple property check

Waqf property check

RERA register



Every free tool
/tools



Services we run
for you
/services



The LandLens
suite
/landlens/one



Every claim in this document traces back to a government record.

Legal opinions, due diligence and title verification

Building plan, layout and sub-division approvals

Completion and occupancy certificates, regularisation

Escrow, negotiation and NRI property management

Land survey, soil testing, architecture and construction

Verified RealEstate
3/350/2 Mettukuppam,
OMR Thoraipakkam,
Chennai 600 097, India
hello@verified.realestate
+91 9996 12 9996

Prepared from the registers named on the page each finding sits on. Where a register could not be read, this document says so in its place rather than leaving the gap to be read as a clean result.

