Verified RealEstate™

RE REGULATORY RECORD

RERA Document

The document as the regulator published it, reproduced in full behind this page.

Published for reference. The authority's own register is the operative record.

Verified RealEstate™
3/350/2 Mettukuppam,
OMR Thoraipakkam,
Chennai 600 097, India

hello@verified.realestate
+91 9996 12 9996
verified.realestate

DIGITALLY VERIFIED RECORD

Form-5

(Certificate for the purpose of completion of Layout Project)

Address of the Project: Survey No: **121/1, 121/2, 123/1B, 123/1C, 123/1D, 123/1E, 123/1F, 123/1G, 123/1H, 123/1I, 123/1J, 7 ACRE 50 CENT, KANIMANGALAM** Village, Hosur Panchayat union & Taluk, Krishnagiri District.

Date: 02.06.2025 From

1) **Dr. SHANTHA PRABAKARAN, W/o Mr. P.S.PRABAKARAN,**
2) **Mrs. PRATHIMA PRABHAKARAN, D/o Mr. P.S.PRABAKARAN,**
3) **Mrs. SWAROOP PRABHAKARAN, D/o Mr. P.S.PRABAKARAN**
   NO: 558/A, 15th CROSS, 16TH MAIN, 4TH SECTOR,
   H.S.R LAYOUT, BANGALORE- 560-102.

Subject: Certificate for: certificate for completion of layout work, Survey No: **121/1, 121/2, 123/1B, 123/1C, 123/1D, 123/1E, 123/1F, 123/1G, 123/1H, 123/1I, 123/1J, 7 ACRE 50 CENT, KANIMANGALAM** Village, Baduthepalli Panchayat, Hosur Panchayat union & Taluk, Krishnagiri District.

Ref :_____(TNRERA Registration Number)

Sir,

I, Er.V.VINOTHKUMAR having License No. 101/2022 (GR -III) had undertaken assignment as an Architect/ Licensed Surveyor for the assessment and verification of development of work done at situated on the Plot bearing Survey No: 121/1, 121/2, 123/1B, 123/1C, 123/1D, 123/1E, 123/1F, 123/1G, 123/1H, 123/1I, 123/1J, KANIMANGALAM village, Baduthepalli Panchayat, Hosur Taluk, Krishnagiri District, demarcated by its boundaries (latitude 12°48'11.8"N and longitude 77°52'07.2"E of the end points) 9.0 M Existing Road in S.No.122, to the North,Village No. 79 (Marasanthiram Village) to the South, S.NO : 121/3, 123/1A & Village No. 79 (Marasanthiram Village) to the East, S.No. 128, S.No.124/2B, S.No.124/2A & Existing Road to the West. SITE Survey No: 121/1, 121/2, 123/1B, 123/1C, 123/1D, 123/1E, 123/1F, 123/1G, 123/1H, 123/1I, 123/1J, KANIMANGALAM village, Baduthepalli Panchayat, Hosur Taluk, Krishnagiri District. Measuring 30350.00 Sq. mts. Being developed by Dr. SHANTHA PRABAKARAN, W/o Mr. P.S.PRABAKARAN & 2 Others

Based on site inspection carried out by me with respect to each of the plot(s) of the aforesaid Layout/ Sub-Division Project, I certify that as on date of this certificate, the project has been developed and completed in all respects as per the Plotting layout plan sanctioned by DEPUTY DIRECTOR TOWN AND COUNTRY PLANING, Krishnagiri District officer, Hosur vide Layout is assigned as L.P/H.N.T.D.A.(K.D) (SWP) NO: 196/2024 AND PLANNING PERMISSION (SWP) No: 79/2024) dated 30.12.2024 including all amenities and facilities as committed by the promoter to the all otters.Stamp, Signature & Name of Architect/ Licensed Surveyor with (Reg. License NO: 101/2022 G-III)

Enclosed: Photographs of all Sides of Site

Yours Faithfully,

V. Vinoth Kumar

Er. V. VINOTHKUMAR M.E (Structural),
Chartered Engineer & Regd. Professional Engineer,
HCMC Govt. Regd. Engineer Reg. No : 01/2022 (RE-GR-III),
DTCP Govt. Regd. Engineer Reg. No : 36/2024 (RE-GR-II),
36/2024 (CE), 26/2022 (RSE-GR-II), 14/2022 (RD),
Yuktha Construction, Shanthi Nagar East,
2nd Cross, HOSUR-635109. Ph. No : 9750381769

THE LANDLENS SUITE

Eight ways to know a piece of land before you pay for it.

This report covers one part of the picture. These cover the rest, drawn from the same government records, for any property in Tamil Nadu.

LandLens One
Ask anything about a property and get an answer grounded in live government records, with the sources shown.
/landlens/one

Verify My Land
Every record check run on one property and returned as a single report.
/landlens/verify-my-land

Legal Opinion
An advocate's written opinion on the title, built on the records we pull for it.
/landlens

One Map
Every layer on one map: the parcel, its boundary, zoning, water bodies and what sits around it.
/landlens/one/map

PriceMap
What land actually changed hands for around this plot, taken from the registered deeds.
/landlens/pricemap

Build Scope
What you are allowed to build here: floor space, height, coverage and setbacks.
/landlens/build-scope

Property Tracker
Watch a property and hear about it when something new is registered against it.
/landlens/property-tracker

Deal Room
Run the transaction in one place: documents, stamping, signatures and the parties.
/landlens/deal-room

FREE TOOLS · NO ACCOUNT NEEDED

Twenty-four checks you can run yourself, at no cost.

Records and verification

The registers themselves, read for you.

- Encumbrance Certificate
- Patta and Chitta
- Field Measurement Sketch
- EC Analyzer
- Bank charge check
- Court case search
- Seller background check
- Approval check by survey

Value and duty

What it is worth and what it costs to register.

- Guideline value by street
- Guideline value by survey
- Stamp duty and registration fees
- Capital gains
- Floor space index
- Area unit converter

Zoning and land use

What the plan says can happen on this land.

- Land use zone finder
- CMDA land use check
- Coastal regulation zone
- Master plan check
- Water bodies finder
- Airport height clearance

Registers and directories

Who holds it, and which office keeps the record.

- Find your registering office
- Temple property check
- Waqf property check
- RERA register

Every free tool
/tools

Services we run for you
/services

The LandLens suite
/landlens/one

Verified RealEstate™

Every claim in this document traces back to a government record.

- Legal opinions, due diligence and title verification
- Building plan, layout and sub-division approvals
- Completion and occupancy certificates, regularisation
- Escrow, negotiation and NRI property management
- Land survey, soil testing, architecture and construction

Verified RealEstate
3/350/2 Mettukuppam,
OMR Thoraipakkam,
Chennai 600 097, India
hello@verified.realestate
+91 9996 12 9996

Prepared from the registers named on the page each finding sits on. Where a register could not be read, this document says so in its place rather than leaving the gap to be read as a clean result.