Verified RealEstate™

RE REGULATORY RECORD

RERA Document

The document as the regulator published it, reproduced in full behind this page.

Published for reference. The authority's own register is the operative record.

Verified RealEstate™
3/350/2 Mettukuppam,
OMR Thoraipakkam,
Chennai 600 097, India

hello@verified.realestate
+91 9996 12 9996
verified.realestate

DIGITALLY VERIFIED RECORD

Er S. JAGADESH KANNAN,M.E(Struct),PE,MIE,FIV,
CONSULTING STRUCTURAL ENGINEER
PROFESSIONAL ENGINEER
CHARTERED ENGINEER (M-1630045) & APPROVED VALUER (F-24610)

Date:14.08.2026

STABILITY CERTIFICATE
(To be furnished while filing application for registration of building)

The detailed engineering and structure design of the proposed apartment building "CLASSIC MANGALAM" Block-1 having (Stilt + 5 Floors) with 20 Dwelling Units at S.F.No.190/1A1B, Andipalayam village, Tiruppur Municipality & Tiruppur South Taluk, Tiruppur District has been done by me based on the report of geotechnical investigation (soil test) done by Techlead Consulatant & Engineers, Report No.TCE-ST-78/2026-2027, Dated 09.05.2026 and considering the functional requirement of the building.

2. It is certified that among other factors, the proposed building has been designed to resist earthquake. I have checked various parameters and found that the proposed building would be safe.

3. I further certify that:

(i) The minimum grade of concrete is M25.


(ii) The design and analysis has been done using the code of practice for plain and reinforced concrete as per IS 456, design loads as per IS Codes No.875 and design of earthquake resistant structure as per IS Code No.1893.

4. The building will be safe and sound when used for the purpose for which it is designed.


Stamp and Signature

Er. S. JAGADESH KANNAN ME(Struct), PE, MIE, FIV.,
CHARTERED CIVIL ENGINEER (M-1630045)
REGISTERED STRUCTURAL ENGINEER
REGD No : TD/RSE/Gr-I/2025/02/002
1 B, OLD DAMU NAGAR, PULIYAKULAM,
COIMBATORE - 641 045


31 B, OLD DAMU NAGAR, PULIYAKULAM, COIMBATORE - 641 045.
Mobile : +91 - 98942 44487, Office : 0422 - 2324487, E-mail : jagadeshkannan@gmail.com



FOOTING LAYOUT



SECTION - AA




TYPICAL PLAN OF FOOTING

SECTION - BB


SCHEDULE OF FOOTINGS

FOOTING TYPE	FOOTING SIZE	DEPTH ('D')	BOTTOM STEEL		TOP STEEL		
			SHORTER	LONGER	SHORTER		
	3800 x 3200	830	Y12@100C/C	Y12@100C/C	-		
	3600 x 3100	750	Y12@100C/C	Y16@100C/C	-		
	3100 x 2700	680	Y12@100C/C	Y12@100C/C	-		
	2700 x 2300	680	Y12@100C/C	Y12@100C/C	-		
	2500 x 2200	600	Y12@100C/C	Y12@100C/C	-		
F6	2300 x 2000	530	Y12@100C/C	Y12@100C/C	-	-	-
F7	2000 x 1800	450	Y12@100C/C	Y12@100C/C	-	-	REMARKS
F8	1800 x 1500	380	Y12@100C/C	Y12@100C/C	-	LONGER	-
~~F1~~ F9	1200 x 1200	300	Y10@150C/C	Y10@150C/C	-	-	-
~~F2~~ CF1	6700 x 5700	750	Y12@100C/C	Y12@100C/C	Y12@100C/C	Y12@100C/C	COMBINED FOOTING
~~F3~~ CF2	4300 x 3800	750	Y12@100C/C	Y12@100C/C	Y12@100C/C	Y12@100C/C	COMBINED FOOTING
~~F4~~ CF3	3800 x 3200	680	Y12@100C/C	Y12@100C/C	Y12@100C/C	Y12@100C/C	COMBINED FOOTING
~~F5~~ CF4	3300 x 2700	450	Y12@100C/C	Y12@100C/C	Y12@100C/C	Y12@100C/C	COMBINED FOOTING



FOOTING BEAM
(FB1) DETAIL

FOOTING BEAM
(FB2) DETAIL



SECTION - CC

Er. S. JAGADESH KANNAN ME(Struct), PE, MIE, FIV.,
CHARTERED CIVIL ENGINEER (M-1630045)
REGISTERED STRUCTURAL ENGINEER
REGD No : TD /RSE/Gr-1/2025/02/002
1 B, OLD DAMU NAGAR, PULIYAKULAM,
COIMBATORE - 641 045

THE LANDLENS SUITE

Eight ways to know a piece of land before you pay for it.

This report covers one part of the picture. These cover the rest, drawn from the same government records, for any property in Tamil Nadu.

LandLens One
Ask anything about a property and get an answer grounded in live government records, with the sources shown.
/landlens/one

Verify My Land
Every record check run on one property and returned as a single report.
/landlens/verify-my-land

Legal Opinion
An advocate's written opinion on the title, built on the records we pull for it.
/landlens

One Map
Every layer on one map: the parcel, its boundary, zoning, water bodies and what sits around it.
/landlens/one/map

PriceMap
What land actually changed hands for around this plot, taken from the registered deeds.
/landlens/pricemap

Build Scope
What you are allowed to build here: floor space, height, coverage and setbacks.
/landlens/build-scope

Property Tracker
Watch a property and hear about it when something new is registered against it.
/landlens/property-tracker

Deal Room
Run the transaction in one place: documents, stamping, signatures and the parties.
/landlens/deal-room

FREE TOOLS · NO ACCOUNT NEEDED

Twenty-four checks you can run yourself, at no cost.

Records and verification

The registers themselves, read for you.

- Encumbrance Certificate
- Patta and Chitta
- Field Measurement Sketch
- EC Analyzer
- Bank charge check
- Court case search
- Seller background check
- Approval check by survey

Value and duty

What it is worth and what it costs to register.

- Guideline value by street
- Guideline value by survey
- Stamp duty and registration fees
- Capital gains
- Floor space index
- Area unit converter

Zoning and land use

What the plan says can happen on this land.

- Land use zone finder
- CMDA land use check
- Coastal regulation zone
- Master plan check
- Water bodies finder
- Airport height clearance

Registers and directories

Who holds it, and which office keeps the record.

- Find your registering office
- Temple property check
- Waqf property check
- RERA register

Every free tool
/tools

Services we run for you
/services

The LandLens suite
/landlens/one

Verified RealEstate™

Every claim in this document traces back to a government record.

- Legal opinions, due diligence and title verification
- Building plan, layout and sub-division approvals
- Completion and occupancy certificates, regularisation
- Escrow, negotiation and NRI property management
- Land survey, soil testing, architecture and construction

Verified RealEstate
3/350/2 Mettukuppam,
OMR Thoraipakkam,
Chennai 600 097, India
hello@verified.realestate
+91 9996 12 9996

Prepared from the registers named on the page each finding sits on. Where a register could not be read, this document says so in its place rather than leaving the gap to be read as a clean result.