

PP

APPROVAL RECORD

Planning Permission

Erwadi

Ramanathapuram district, Tamil Nadu

APPROVAL TYPE

Building Plan

ISSUING AUTHORITY

Rural Panchayat

PURPOSE

Residential

The approval as the planning authority issued it, reproduced in full behind this page.

An approval speaks to what was sanctioned, not to what was built. Completion is a separate record.



STATUS : **Verified**

APPLICATION DETAILS

1	APPLICANT NAME	Syed Sirajudeen	2	APPLICATION DATE	10/01/2024
3	APPLICATION NUMBER	39897-2024-LI	4	APPLICATION TYPE	Permit
5	OCCUPANCY TYPE	Residential	6	DCR NUMBER	DCR120241AWSG
7	REGISTERED ARCHITECT/ENGINEER	-	8	DEVELOPMENT TYPE	New Construction

PLOT DETAILS

1	SURVEY NO	173/11F2			
2	PLOT NO	173/11F2	3	PATTA NO	2030
4	TALUK	Keelakarai	5	DISTRICT	Ramanathapuram
6	PLOT AREA (As per declaration) in m ²	101.26	7	PLOT AREA (As per measurement) in m ²	101.26
8	AVERAGE WIDTH OF PLOT in m	6.17	9	AVERAGE DEPTH OF PLOT in m	16.41
10	ROAD WIDTH in m	4.88	11	SURRENDER ROAD WIDTH AREA in m ²	0.00
12	AREA TYPE (Continuous/Economically Weaker Section/Others)	OTHERS	13	DEMOLITION AREA in m ²	0
14	OSR APPLICABLE	NO	15	OSR SURRENDER/ BUYBACK/ RETAIN	

Overall Summary

Total Area

Built Up Area in m ²	Carpet Area in m ²	Covered Area in m ²	FSI Area in m ²	Non FSI Area in m ²
121.25	0.00	0.00	115.92	5.33

Non FSI Area Details(Proposed)

Area Details	Area in m ²
Head Room Area	5.33
Total	5.33

Plot Area Details

Description	Area in m ²
-------------	------------------------

Description	Area in m ²
As At Site	101.26
FMB or PLR	101.26
As Per Document	101.26

Block Wise Summary

Block No 1 - Proposed Details

Floor	Occupancy/Sub Occupancy	Floor Area in m ²	Deduction Area in m ²	FSI Area in m ²	Non FSI Area in m ²	Carpet Area in m ²
0	Individual residence	57.96	0	57.96	0	0
1	Apartment / Service apartments	57.96	0	57.96	0	0
Total		115.92	0.00	115.92	0.00	0.00
1. Covered Area is 0.00 m ² 2. Height of building is 6.94 m 3. Head Room Area (Non FSI Area) is 5.33 m ² 4. Total Non FSI Area is 5.33 m ²						

Common - Scrutiny Details

1.No. of Blocks

Description	Provided	Status
Total Number Of Blocks	1	Verified

2.FSI

As per TNCDDBR	Occupancy	Area Type	Road Width	Required	Provided	Status
Part VI Pt.35 / pt.36/ pt.37/ pt.38/ pt.39	Residential	OTHERS	4.88	<= 2	1.145	Verified

3.Floor Units

Block	Floor	Unit Number	Unit Area
Block 1	Floor 0	1	57.96 Sq.m
Block 1	Floor 1	1	57.96 Sq.m

4.Parking

As per TNCDDBR	Description	Required	Provided	Status
Annexure iv - part I-13,17,b,part II-A,C	Two wheeler parking dimension	1 M x 1.8 M	Out of 3 parking 0 parking violated dimension.	Verified
Annexure iv - part I-13,17,b,part II-A,C	Car Parking	0	0	Verified
Annexure iv - part I-13,17,b,part II-A,C	Two Wheeler Parking	2	3	Verified

5.Over Head Tanks

As per TNCDDBR	Description	Provided	Status
Part VII , 54(4),Annexure XV, 5(b)	Over Head Tank	Over Head Tank provided	Verified

6.Bathroom Water Closets

As per TNCDDBR	Description	Required	Provided	Status
----------------	-------------	----------	----------	--------

As per TNCDBR	Description	Required	Provided	Status
Part vii-pt52-7	Bathroom Water Closets	Height >= 2.1, Area >= 2.4, Width >= 1.2	Height >= 2.91, Area >= 3.00, Width >= 1.20	Verified
Part vii-pt52-7	Bathroom Water Closets	Height >= 2.1, Area >= 2.4, Width >= 1.2	Height >= 2.91, Area >= 3.00, Width >= 1.20	Verified

7.Parapet

As per TNCDBR	Description	Required	Provided	Status
Part VII , 52(13)	Parapet	Height >= 1.2 and height <= 1.5	Height >= 1.22 and height <= 1.22	Verified

8.Solar

As per TNCDBR	Description	Required	Provided	Status
Part VI 44(2)	Solar Assisted Water Heating / Lighting system		Defined in the plan.	Verified

9.No. of Dwelling units

Description	Provided	Status
Total Dwelling units	4	Verified

10.Height of Building

As per TNCDBR	Description	Required	Provided	Status
Part VI Pt.35 / pt.36/ pt.37/ pt.38/ pt.39	Height of Building for Block 1	12m / G+2 or Stilt +3 / up to 16 Dwelling Units	6.94m / 2 Floors / 4 Dwelling units	Verified

11.Collection and disposal of Solid and Liquid Waste

As per TNCDBR	Description	Field Verified	Status
part vi-pt 35-17	Collection and disposal of solid and liquid Waste	Defined in the Plan.	Verified

12.Rain Water Harvesting

As per TNCDBR	Description	Provided	Status
Annexure XXII-A	Rain Water Harvesting	Defined in the plan	Verified

13.North Direction

As per TNCDBR	Description	Provided	Status
part ii - 8 -iii-(I)	North Direction	North directions provided	Verified

14.Location Plan

As per TNCDBR	Description	Provided	Status
part ii - 8 -i	Location Plan	Location plans provided	Verified

15.Toilet Ventilation

As per TNCDBR	Description	Required	Provided	Status
part vii-52(16a)	Toilet Ventilation	Min 0.5 Sq.m	0.58 Sq.m	Verified

16.Road Width

As per TNCDBR	Description	Occupancy	Required	Provided	Status
Part VI	Road Width	Individual residence	>=3m	4.88m	Verified

Block 1 - Scrutiny Details

1.Setback

As per TNCDBR	Setback	Occupancy	Level	Field Verified	Required	Provided	Status
Part VI, Pt.35 / pt.36/ pt.37/ pt.38/ pt.39	Front	Apartment / Service apartments,Individual residence	0	Minimum distance	1.5	1.50	Verified
Part VI, Pt.35 / pt.36/ pt.37/ pt.38/ pt.39	Rear	Individual residence	0	Minimum distance	0	1.01	Verified
Part VI, Pt.35 / pt.36/ pt.37/ pt.38/ pt.39	Side Setback 1	Apartment / Service apartments,Individual residence	0	Minimum distance	1	1.0	Verified
Part VI, Pt.35 / pt.36/ pt.37/ pt.38/ pt.39	Side Setback 2	Apartment / Service apartments,Individual residence	0	Minimum distance	1	1.0	Verified

2.General Stair - Mid landing

As per TNCDBR	Floor	Description	Required	Provided	Status
Part VII , 52(17)	floor 0	Minimum width for general stair 1 mid landing	0.75	0.91	Verified
Part VII , 52(17)	floor 1	Minimum width for general stair 1 mid landing	0.75	0.91	Verified

3.General Stair - Number of risers

As per TNCDBR	Floor	Description	Required	Provided	Status
Part VII , 52(17)	floor 0	Maximum no of risers required per flight for general stair 1 flight 1	15	7	Verified
Part VII , 52(17)	floor 0	Maximum no of risers required per flight for general stair 1 flight 2	15	7	Verified
Part VII , 52(17)	floor 1	Maximum no of risers required per flight for general stair 1 flight 1	15	9	Verified
Part VII , 52(17)	floor 1	Maximum no of risers required per flight for general stair 1 flight 2	15	9	Verified

4.General Stair - Tread width

As per TNCDBR	Floor	Description	Required	Provided	Status
Part VII , 52(17)	floor 0	Minimum tread for general stair 1 flight 1	0.25	0.33	Verified
Part VII , 52(17)	floor 0	Minimum tread for general stair 1 flight 2	0.25	0.33	Verified
Part VII , 52(17)	floor 1	Minimum tread for general stair 1 flight 1	0.25	0.25	Verified
Part VII , 52(17)	floor 1	Minimum tread for general stair 1 flight 2	0.25	0.25	Verified

5.General Stair - Width

As per TNCDBR	Floor	Description	Required	Provided	Status
---------------	-------	-------------	----------	----------	--------

As per TNCDBR	Floor	Description	Required	Provided	Status
Part VII , 52(17)	floor 0	Minimum width for general stair 1 flight 1	0.75	0.91	Verified
Part VII , 52(17)	floor 0	Minimum width for general stair 1 flight 2	0.75	0.91	Verified
Part VII , 52(17)	floor 1	Minimum width for general stair 1 flight 1	0.75	0.91	Verified
Part VII , 52(17)	floor 1	Minimum width for general stair 1 flight 2	0.75	0.91	Verified

6.Kitchen

As per TNCDBR	Description	Floor	Required	Provided	Status
part vii-pt52-6	Minimum height of kitchen	floor 0	2.75m	2.91m	Verified
part vii-pt52-6	Total area of kitchen	floor 0	10Sq.m	16.02Sq.m	Verified
part vii-pt52-6	Minimum Width of kitchen	floor 0	1.8m	2.40m	Verified
part vii-pt52-6	Minimum height of kitchen	floor 1	2.75m	2.91m	Verified
part vii-pt52-6	Total area of kitchen	floor 1	10Sq.m	16.02Sq.m	Verified
part vii-pt52-6	Minimum Width of kitchen	floor 1	1.8m	2.40m	Verified

7.Kitchen Ventilation

As per TNCDBR	Description	Required	Provided	Status
part vii-52(16a)	Light and Ventilation	Minimum 1/8th of the floor area	Ventilation area 4.62 of Kitchen Area 16.02 at floor 0	Verified
part vii-52(16a)	Light and Ventilation	Minimum 1/8th of the floor area	Ventilation area 4.62 of Kitchen Area 16.02 at floor 1	Verified

8.Plinth

As per TNCDBR	Description	Required	Provided	Status
part vii-pt52-1	Minimum plinth height	>= 0.45m	0.91m	Verified

9.Room

As per TNCDBR	Description	Floor	Required	Provided	Status
part vii-pt52-5,6,9,10	Minimum height of room	floor 0	2.75m	2.91m	Verified
	Minimum Width of room	floor 0	2.1m	2.50m	Verified
part vii-pt52-5,6,9,10	Minimum height of room	floor 1	2.75m	2.91m	Verified
	Minimum Width of room	floor 1	2.1m	2.50m	Verified

11.Stair Headroom

As per TNCDBR	Description	Required	Provided	Status
part vii-pt52-17(d)	Minimum clear of stair head-room	2.2	2.75	Verified
part vii-pt52-17(d)	Minimum Area of head-room	>0 Sq.m	5.33 Sq.m	Verified

12.Ventilation

As per TNCDBR	Description	Required	Provided	Status
---------------	-------------	----------	----------	--------

As per TNCDBR	Description	Required	Provided	Status
part vii-52(16a)	Light and Ventilation	Minimum 1/8th of the floor area	Ventilation area 4.71 of Room Area 16.54 at floor 0	Verified
part vii-52(16a)	Light and Ventilation	Minimum 1/8th of the floor area	Ventilation area 4.71 of Room Area 16.54 at floor 1	Verified

This report is generated based on the Applicant Declaration and a provided drawing. The drawing has been verified with TNCDBR rules and final decision on approval will be taken by Department officials. Completion Certificate will not be issued if any deviation from the submitted drawing more than tolerance Limits.

Eight ways to know a piece of land before you pay for it.

This report covers one part of the picture. These cover the rest, drawn from the same government records, for any property in Tamil Nadu.

LandLens One

Ask anything about a property and get an answer grounded in live government records, with the sources shown.

[/landlens/one](#)



Verify My Land

Every record check run on one property and returned as a single report.

[/landlens/verify-my-land](#)



Legal Opinion

An advocate's written opinion on the title, built on the records we pull for it.

[/landlens](#)



One Map

Every layer on one map: the parcel, its boundary, zoning, water bodies and what sits around it.

[/landlens/one/map](#)



PriceMap

What land actually changed hands for around this plot, taken from the registered deeds.

[/landlens/pricemap](#)



Build Scope

What you are allowed to build here: floor space, height, coverage and setbacks.

[/landlens/build-scope](#)



Property Tracker

Watch a property and hear about it when something new is registered against it.

[/landlens/property-tracker](#)



Deal Room

Run the transaction in one place: documents, stamping, signatures and the parties.

[/landlens/deal-room](#)



Twenty-four checks you can run yourself, at no cost.

Records and verification

The registers themselves, read for you.

Encumbrance Certificate

Patta and Chitta

Field Measurement Sketch

EC Analyzer

Bank charge check

Court case search

Seller background check

Approval check by survey

Zoning and land use

What the plan says can happen on this land.

Land use zone finder

CMDA land use check

Coastal regulation zone

Master plan check

Water bodies finder

Airport height clearance

Value and duty

What it is worth and what it costs to register.

Guideline value by street

Guideline value by survey

Stamp duty and registration fees

Capital gains

Floor space index

Area unit converter

Registers and directories

Who holds it, and which office keeps the record.

Find your registering office

Temple property check

Waqf property check

RERA register



Every free tool
/tools



Services we run
for you
/services



The LandLens
suite
/landlens/one



Every claim in this document traces back to a government record.

Legal opinions, due diligence and title verification

Building plan, layout and sub-division approvals

Completion and occupancy certificates, regularisation

Escrow, negotiation and NRI property management

Land survey, soil testing, architecture and construction

Verified RealEstate
3/350/2 Mettukuppam,
OMR Thoraipakkam,
Chennai 600 097, India
hello@verified.realestate
+91 9996 12 9996

Prepared from the registers named on the page each finding sits on. Where a register could not be read, this document says so in its place rather than leaving the gap to be read as a clean result.

